

GREG BELL Licutenant Governor

# State of Utah

### DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Representatives Present During the Inspection: OGM Karl Houskeeper



## **Inspection Report**

Permit Number:	C0150032		
Inspection Type:	PARTIAL		
Inspection Date:	Thursday, August 05, 2010		
Start Date/Time:	8/5/2010 9:30:00 PM		
End Date/Time:	8/5/2010 12:30:00 PM		
Last Inspection:	Thursday, July 08, 2010		

Inspector: Karl Houskeeper,

Weather: Cloudy, Temp. 70 Deg. F. InspectionID Report Number: 2448

**Types of Operations** 

Accepted by: jhelfric

8/12/2010

Permitee: GENWAL RESOURCES INC Operator: GENWAL RESOURCES INC Site: CRANDALL CANYON MINE

Address: PO BOX 910, EAST CARBON UT 84520-0910

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

**Current Acreages** 

<b>Total Permitted</b>	6,235.80	
<b>Total Disturbed</b>	27.15	
Phase I		
Phase II		
Phase III		

**Mineral Ownership** 

✓ Federal ✓ Underground State Surface

County ☐ Loadout Processing

Other Reprocessing Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Dana Marrelli UtahAmerican Energy was on site during the inspection along with workers from Scamp Construction.

Purpose of the inspection was to observe the cleaning of the iron treatment pond and placement of iron sediment and water into the sediment pond.

Inspector's Signature:

Date

Thursday, Augu

Karl Houskeeper,

Inspector ID Number: 49

Permit Number: C0150032 Inspection Type: PARTIAL

Inspection Date: Thursday, August 05, 2010

Page 2 of 3

#### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers				
3.	Topsoil				
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0150032 Inspection Type: PARTIAL

Inspection Date: Thursday, August 05, 2010

Page 3 of 3

### 4.b Hydrologic Balance: Sediment Ponds and Impoundments

Viewed the sediment pond and the iron laden sediment and water being placed in the sediment pond from cleaning of the iron treatment pond. Pictures were taken and uploaded to the picture database. The water level of the pond is 3.9' below the 10 year 24 hour marker. The measurement was taken from the top of the red band to water level. The water in the pond is chocolate in color from the advent of recent rain storm events. Orange laden ( iron) sediment water form the iron treatment pond cleaning was observed at the entrance diversion into the sediment pond, but dissipates into the chocolate colored water immediately upon entrance.